

Fire Extinguisher Certificate of Inspection

Service Address

Peaslake Village Hall
Walking Bottom
Peaslake
Guildford, Surrey
GU5 9RR

Invoice Address

Peaslake Village Hall
c/o Tony Robinson
Birches House; Birches Lane
Gomshall, Surrey
GU5 9QR

**This is to certify that the Fire Fighting Equipment at the above service address was serviced on 20 October 2025
by Allan Clark against SO25-049542.**

**We hereby certify that, apart from non-conforming components as recorded below, all of the equipment has been
serviced in accordance with BS 5306-3:2017*.**

Qty	Description	Inspected Good	Extended Service	Recharge	Service Exchange	Non Conforming	New Installed
2	CO2	2	0	0	0	0	0
3	Fire Blanket	3	0	0	0	0	0
6	Water	5	0	0	0	1	0

Corrective Action

Customer has requested this email be updated as new main contact email address:

gerry.reffo@shereparishcouncil.gov.uk

Serviced all fire extinguishers and fire blankets on site to current British
standards.

Replaced O rings, gauge seals and paddle seals.

The following fire fighting equipment has been replaced due to having reached
the end of serviceable life:

1x 6L Water extinguisher

1x Extinguisher removed for environmental disposal.

P50 Fire Extinguishers are visually inspected in line with manufacturers recommendations and are not covered under the BAFE modular scheme



Churches Fire Security Ltd. Fire House Mayflower Close Chandlers Ford SO53 4AR

Tel: 0370 608 4350 Fax: 0870 608 4351 customer.services@churchesfire.com www.churchesfire.com

Fire Extinguisher Certificate of Inspection

Service Address

Peaslake Village Hall
Walking Bottom
Peaslake
Guildford, Surrey
GU5 9RR

Invoice Address

Peaslake Village Hall
c/o Tony Robinson
Birches House; Birches Lane
Gomshall, Surrey
GU5 9QR

The following fire fighting equipment needs installing to meet current British standards as per the quote:

2x 2kg Co2 extinguishers on brackets with signage either end of corridor.

I hereby certify that the technician has explained the works carried out and that I am duly authorised to approve these works. I understand that it is the duty of the responsible person, under fire legislation, to provide sufficient fire protection at all times.

Name: Jim Colin

Signature: 

P50 Fire Extinguishers are visually inspected in line with manufacturers recommendations and are not covered under the BAFE modular scheme



British Automatic Fire Extinguisher Association
bafsa

GENT 24
Customer Support

NOTIFIER[®]
by Honeywell



Churches Fire Security Ltd.

Fire House

Mayflower Close

Chandlers Ford

SO53 4AR

Tel: 0370 608 4350 Fax: 0870 608 4351 customer.services@churchesfire.com www.churchesfire.com

*Unless agreed otherwise with the customer